

CASE STORY

Senvion MM92 2MW Wind Turbine (08008)


Background

Wind turbine was operating for six months prior to the installation of MetalSCAN. Once MetalSCAN was installed, operation continued for one month without incident.

Event Description

One month after installation, MetalSCAN detected debris increases and the cumulative counts crossed the warning limit (10% of the alarm limit) triggering a videoscope inspection. The high rate of accumulation suggested the possibility of high-speed bearing damage. The videoscope inspection confirmed damage to the inner race of the high-speed bearing. As a result, the wind turbine was stopped and the high-speed bearing was replaced uptower. The wind turbine was restarted and the MetalSCAN trend indicated a healthy gearbox.

Time History of Events



Damaged High - Speed Bearing

BENEFITS

- ✓ MetalSCAN trend enabled maintainers to repair damaged bearing uptower
- ✓ Secondary damage avoided

ONLY TIME SINCE METALSCAN INSTALLATION SHOWN

LONG LIVE EQUIPMENT



Head Office
1011 Polytek Street
Ottawa ON K1J 9J3
Canada

Halifax Office
65 John Savage Avenue, Unit 5
Dartmouth NS B3B 2C9
Canada

St. John's Office
146a Glencoe Drive
Mount Pearl NL A1N 4S9
Canada

Worldwide
+1 613 744 3530
North America
1 800 363 8658

gastops.com
C009678_000